MAY 2 7 2004 P.

10/792,357

cofc

David M. Solak 4805 Maple Hill Drive Seven Hills, Ohio 44131 d.solak@sbcglobal.net May 24, 2004

Certificate

JUL 0 7 2004

of Correction

Dear Patent Agent,

I respectfully apologize for not including the patent application number. Here are the original sheets I was sent on May 24, 2004. Enclosed is a copy of the receipt I received from the PTO. I am hoping this is what you need. The patent has not been issued yet. The correction involves the placement of "fire ignites here" on the block diagram. I believe I placed the phrase in the wrong location on the original patent application. You will find three drawings of the block diagram with the "fire ignites here" in the proper location. I hope this is the acceptable way to remedy this problem. If not, please contact me at your convenience.

aval Molah

22387 U.S. PTO 10/792357 ✓

RECEIVED

JUL 1 6 2004

Technology Center 2600

030404

Respectfully,
David M. Solak
Engineer/Inventor

RECEIVED

JUL 1 6 2004

MAY 2 7 2004

FORM PTOL-396 (8/75)

UNITED STATES PATENT AND TRADEMARK OFFICE

Technology Center 2600

COMMISSIONER FOR PATENTS
UNITED STATES PATENT AND TRADEMARK-OFFICE
P.O. BOX 1450
ALEXANDRIA, VA 22313-1450

WWW.uspto.gov

Paper No.:

MAILING DATE

Cartificate

APR 3 0 2004

Of Correction

PATENT NO.

PATENT DATE

4/26/04

PATENTEE

DAVID M. SOUAK

NOTIFICATION OF RETURN OF PAPERS RE REQUEST FOR CERTIFICATE OF CORRECTION

The request for a Certificate of Correction in the above-identified patent is returned herewith, together with the PTOL-1050 (SB/44) forms (if submitted), for the reason(s) checked below.
1. The request is unsigned. The request must be properly signed before it will be considered.
2. The request does not specifically designate the column and line numbers wherein the errors appear in the patent. A substitute request providing this information is required, for proper consideration.
3. The FORM PTOL-1050 (SB/44) submitted with your request is not suitable for printing purposes. See the instructions on the blank Form PTO-1050, enclosed.
4. The Patent No., as shown on papers attach, appears to be incorrect, because: 1. The Patent No. on the request and on the PTO-1050 do not agree.
b. The name of the patentee on the patented file does not agree with that shown on the enclosed papers
5. The record reveals that there is no power of attorney to you in this case. A written power or authorization from the patentee, or assignee, if any, must be submitted, before the request may be considered.
6. The request cannot be considered, because the paper indicated below was filed on AFTER payment of the issue fee: [See 37 CFR 1.313(B.].
a. Amendment purported to be under Rule 312.
b. Assignment.
c. Priority papers.
d. Other (identify)
7. Other: NO PATENT NUMBER
A. PLEASE RETURN A COPY OF THIS LETTER TOGETHER WITH THE ENCLOSED PAPERS AS CORRECTED TO ENSURE EXPEDIENT ASSOCIATION WITH THE FILE
B. Enclosed are copies of PTOL-1050 for use in typing the subject matter to be printed on the Certificate. This will avoid delay in handling request (See 862 O.G.2).
mark
ecisions and Certificate of Correction Branch



RECEIVED

Technology Center 2600

The following received today:

7 sheets formal drawings, small entity declaration cover sheets and check #3%/6 for \$ #3%/6Patent application of David M. Solak for Abstract, Declaration signed March 1, 2004 "RF SMOKE SENSING SYSTEM WITH Consisting of 5 sheets Description, Claims, CHRISTMAS ORNAMENT TRANSMITTER," INTEGRATED SMOKE/HEAT SENSING

for \$ 470.00










FIG. 5






FIG. 5






FIG. 5






FIG. 5

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

DATED

9/26/04

INVENTOR(S): DAVID M. SOLAK

APPLICATION/ DEAWINGS

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

NON-WINTER-HOLIDAY SEASON




FIG. 5

Dear Ms or Sir,

I respectfully request to make a correction on my patent application before it possibly issues. If this is not the proper time or way to make a correction discard this document and I will make the correction when the proper time arises if the patent is issued.

Sincerely,

David M. Solak

Engineer/Inventor

Application Title: Smoke Sensing System With Integrated Christmas Tree Ornament Fire Detector

MAILING ADDRESS OF SENDER: 4805 MAPIE HILLDIZ. PATENT NO.

David M Solah

SEVENHIlls, Ohio 44131-5916

No. of additional copies

cl. solake sbeglubal. NET

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

DATED

4/26/09

INVENTOR(S): DAVID M. SOLAK

APPLICATION/ DEAWINGS

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

NON-WINTER-HOLIDAY SEASON




FIG. 5

Dear Ms or Sir.

I respectfully request to make a correction on my patent application before it possibly issues. If this is not the proper time or way to make a correction discard this document and I will make the correction when the proper time arises if the patent is issued.

Sincerely,

David M. Solak Engineer/Inventor

Application Title: Smoke Sensing System With Integrated Christmas Tree Ornament Fire Detector

MAILING ADDRESS OF SENDER: 4805 MAPLE HILLDR. PATENT NO. 10/792357

No. of additional copies

SEVENHIlls, Ohio 44131-5916 cl. solake sucglubal. NET

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentially is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450, DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

DATED

4/26/09

INVENTOR(S): DAVID M. SOLAK

APPLICATION/ DEAWINGS

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

NON-WINTER-HOLIDAY SEASON




FIG. 5

Dear Ms or Sir.

I respectfully request to make a correction on my patent application before it possibly issues. If this is not the proper time or way to make a correction discard this document and I will make the correction when the proper time arises if the patent is issued.

Sincerely,

David M. Solak Engineer/Inventor

Application Title: Smoke Sensing System With Integrated Christmas Tree Ornament Fire Detector

MAILING ADDRESS OF SENDER:

4805 MAPLE HILLDR. PATENT NO. 10/792357 SEVENHIlls, Ohio 44131-5916 cl. solake sbeglubal NET

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer. U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.